



## Cotizacion

CARLOS ALFREDO TRUJILLO LUGO

PLATINUM SERVICE

EMILIANO ZAPATA 1340 PTE. LOS PINOS C.P. 80128

CULIACAN, SINALOA R.F.C. TULC781111MJ9 Tel.:2579343

ID: 4912

Fecha: 03-Sep-2024

Cliente: KURODA

Vendedor: ADMINISTRADOR . .

| Articulo                 | Unidad | Cantidad | Precio            | Importe         |
|--------------------------|--------|----------|-------------------|-----------------|
| CONECTOR ELECTRICO       | PZA    | 2.000    | 195.000           | 390.00          |
| TUERCA SUJETADORA        | PZA    | 4.000    | 18.000            | 72.00           |
| GUASA DE PRESION         | PZA    | 4.000    | 12.000            | 48.00           |
| TERMOFIL                 | PZA    | 1.000    | 80.000            | 80.00           |
| ADAPTAR CALAVERA TRASERA | PZA    | 1.000    | 600.000           | 600.00          |
|                          |        |          | <b>Sub-Total:</b> | <b>1,190.00</b> |
|                          |        |          | <b>IVA:</b>       | <b>190.40</b>   |
|                          |        |          | <b>Total:</b>     | <b>1,380.40</b> |

### Comentario

SERVICIO A REALIZAR A TOYOTA HILLUX, MODELO 2017, PLACA UK-16-221, SERIE MR0EX8CB1H1398632, KC-38.