



Cotizacion

CARLOS ALFREDO TRUJILLO LUGO

PLATINUM SERVICE

BLVD. EMILIANO ZAPATA 1340 PTE. LOS PINOS C.P. 80128

CULIACAN, SINALOA R.F.C. TULC781111MJ9 Tel.:2579343

ID: 1108 Fecha: 25-Oct-2018

Cliente: PUBLICO GENERAL

PUBLICO GENERAL

Vendedor: ADMINISTRADOR . .

Articulo	Unidad	Cantidad	Precio	Importe
KIT DE CLUTCH	PZA	1.000	5,470.000	5,470.00
RECTIFICAR VOLANTE CLUTCH	PZA	1.000	220.000	220.00
MANO DE OBRA	NO APLICA	1.000	2,000.000	2,000.00
			Sub-Total:	7,690.00
			IVA:	1,230.40
			Total:	8,920.40

Comentario

- SERVICIO PARA DODGE RAM MODELO 2018