



Cotizacion

CARLOS ALFREDO TRUJILLO LUGO

PLATINUM SERVICE

BLVD. EMILIANO ZAPATA 1340 PTE. LOS PINOS C.P. 80128

CULIACAN, SINALOA R.F.C. TULC781111MJ9 Tel.:2579343

ID: 1275

Fecha: 06-Apr-2019

Cliente: KURODA S.A. DE C.V.

Vendedor: ADMINISTRADOR . .

Articulo	Unidad	Cantidad	Precio	Importe
DESMONTAR Y MONTAR TRANSMISION	NO APLICA	1.000	3,000.000	3,000.00
DISCO DE CLUTCH	PZA	1.000	5,912.660	5,912.66
PRENSA DE CLUTCH	PZA	1.000	5,113.270	5,113.27
COLLARIN	PZA	1.000	6,123.290	6,123.29
RECTIFICAR VOLANTE CLUTCH	PZA	1.000	280.000	280.00
			Sub-Total:	20,429.22
			IVA:	3,268.68
			Total:	23,697.90

Comentario

SERVICIO A FREIGHTLINER 360 2010, SERIE: JLMBBH1S9AK008248

NOTA: SON REFACCIONES ORIGINALES DE AGENCIA.