

TARJETA ORDEN DE REPARACIÓN

01/11/2023 15:01:40

NUMERO : 026981 RECEPCION : 05/10/23 12:39 PM STATUS : CERRADA
 TIPO : CITAS PROMESA : 05/10/23 17:15 PM CIERRE : 01/11/2023 02:57:00 PM
 ASESOR : TAPIA CERVANTES PERLA

TIPO VEHICULO: SERIE 500 1524 VEHICULO : CHASIS CABINA HINO MODELO : 2012 PLACAS : UG89179
 SERIE : 3HJFG8JM0CSS12721 COLOR : BLANCO/ROJO C51 MOTOR : J08ETE24833 KMS.: 284,101

CLIENTE : 10095 KURODA SA DE CV TELEFONO : 6677122104
 CORREO : fleyva@kuroda.com

CONDUCTOR : . TELEFONO :
 CORREO : .

OBSERVACIONES

REVISION DE UNIDAD CLUTCH Y AIRE DE LOS FRENOS -

OBSERVACIONES MECANICO

REVISION DE UNIDAD CLUTCH Y AIRE DE LOS FRENOS -

Tipo	Fecha	Referencia	Concepto	Cantidad	Venta
REF	06/10/23	0024179	119257 ACEITE DE MOTOR	12.70	1,173.98
REF	06/10/23	0024179	15613E0110 FILTRO DE ACEITE 1524-1727-2627	1.00	1,062.88
REF	06/10/23	0024179	SZ43018009 EMPAQUE DE TAPON DE CARTER DE ACEITE	1.00	29.06
REF	06/10/23	0024179	23304EV163 FILTRO DE DIESEL S500	1.00	331.43
REF	06/10/23	0024179	23304EV083 PREFILTRO COMBUSTIBLE 1524-1727-2627-263	1.00	295.87
REF	06/10/23	0024179	HLLC001 GALON DE ANTICONGELANTE	3.00	1,270.68
REF	09/10/23	0024204	SZ37120022 BALERO PILOTO SERIE 500 1018 ,1524	1.00	215.90
REF	09/10/23	0024204	31210E0241 PRENSA CLUTCH 1524	1.00	5,287.12
REF	09/10/23	0024204	S312421060 BALERO COLLARIN 1524	1.00	1,306.42
REF	18/10/23	0024302	890720002 SILICON GRIS PARA ALTA TEMPERATURA	2.00	218.94
REF	18/10/23	0024302	12151E0071 EMPAQUE DE CARTER 1524	1.00	2,553.24
REF	18/10/23	0024302	S853531020 CHISGUETERO DE WIPER	2.00	393.56
REF	18/10/23	0024302	S112131880 EMPAQUE DE TAPA DE PUNTERIAS 1524	1.00	3,610.37
REF	18/10/23	0024302	0442AE0040 KIT BIRLO Y TUERCA TRASERO (R) 1524	3.00	1,159.56
REF	18/10/23	0024302	11118E0011 EMPAQUE CAJA BALANCINES	1.00	2,636.30
REF	18/10/23	0024303	13450E0B61 VOLANTE CLUTCH 1524	1.00	38,425.58
REF	18/10/23	0024303	31231E0070 PORTACOLLARIN HINO 500 1524	1.00	2,005.26
REF	18/10/23	0024303	SZ93031104 SZ93031104 HOSE,OIL	1.00	1,284.39
REF	18/10/23	0024303	SZ40710023 CODO LUBRICACION COLLARIN	1.00	120.44
REF	18/10/23	0024303	S312341080 SPRING,RELEASE FORK ANTIRAT	2.00	290.62
REF	20/10/23	0024347	31250E0K20 DISCO DE CLUTCH 1524	1.00	6,333.10
REF	01/11/23	0024458	28226E0102 INTERRUPTOR DE PEDAL DEL FRENO 1018	1.00	1,485.33
MO	07/10/23	00000001	075 TEC JOSE BENJAM - SP SERVICIO DE MANTENIMIENTO 280,000	3.50	3,853.34
MO	21/10/23	00000001	075 TEC JOSE BENJAM - RE5 REMPLAZO EMBRAGUE	7.00	5,600.00
MO	21/10/23	00000001	075 TEC JOSE BENJAM - REP EMPACADA DE CARTER	3.00	2,400.00
MO	21/10/23	00000001	075 TEC JOSE BENJAM - REP INSTALACION DE CHISGUETERO	0.30	240.00
MO	21/10/23	00000001	075 TEC JOSE BENJAM - REP INSTALACION DE EMPAQUE DE TAPA	5.00	4,000.00
MO	21/10/23	00000001	075 TEC JOSE BENJAM - LR LIMPIEZA RADIADOR	2.50	2,000.00
MO	21/10/23	00000001	075 TEC JOSE BENJAM - REP REEMPLAZO DE BIRLO Y TUERCA	2.50	2,000.00
MO	01/11/23	00000001	075 TEC JOSE BENJAM - REP INSTALACION DE INTERRUPTOR	1.00	800.00
30 cargos				SubTotal	92,383.37
				I.V.A.	14,781.34
				I.V.A. Retenido	
				Total	107,164.71

TRABAJOS PROGRAMADOS

Fecha	Descripcion	Mecanico	Horas	Inicio	Terminado	Dif
21/10/2023 09:03 AM	reemplazar embrague	075 TEC JOSE BENJAMIN	4.00	10/10 10:39:24	01/11 02:57:15	154.30